




Nymax™ 600 Polyamide Compounds

Nymax™ 600 Series Polyamide Compounds are based on engineering resins of nylon 6 chemistry that comprise one of the broadest lines of crystalline compounds. Nymax 600 is offered as modified nylon 6, glass-fiber-reinforced, mineral-reinforced and toughened (impact-modified) nylon 6. With this variety of reinforcements and fillers, Nymax 600 is formulated to meet the strong demands of the automotive, consumer durables, industrial/construction and appliance industries. Nymax 600 is offered in natural and black.



Injection Molding Parameters

| Nylon 6 | Blends 600 A | Glass-Reinforced GF 600 A | Mineral-Reinforced MF 600 A | Glass-Fiber/Mineral Reinforced GMF 600 A | Impact-Modified 1108/1010 |
|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--|--------------------------------------|
| Barrel Temperatures* °C (°F) | | | | | |
| Rear Zone | 221 - 249 (430 - 480) | 249 - 277 (480 - 530) | 260 - 277 (500 - 530) | 260 - 277 (500 - 530) | 221 - 254 (430 - 490) |
| Center Zone | 238 - 266 (460 - 510) | 260 - 288 (500 - 550) | 274 - 288 (525 - 550) | 274 - 288 (525 - 550) | 227 - 260 (440 - 500) |
| Front Zone | 243 - 282 (470 - 540) | 271 - 299 (520 - 570) | 274 - 288 (525 - 550) | 274 - 288 (525 - 550) | 238 - 271 (460 - 520) |
| Nozzle | 240 - 280 (465 - 535) | 268 - 296 (515 - 565) | 274 - 288 (525 - 550) | 274 - 288 (525 - 550) | 235 - 268 (455 - 515) |
| Mold Temperature °C (°F) | 49 - 93 (120 - 200) | 49 - 93 (120 - 200) | 49 - 93 (120 - 200) | 49 - 93 (120 - 200) | 49 - 93 (120 - 200) |
| Pack Pressure | 25% - 50% of Injection Pressure | 25% - 50% of Injection Pressure | 25% - 50% of Injection Pressure | 25% - 50% of Injection Pressure | 25% - 50% of Injection Pressure |
| Hold Pressure | 30% of Injection Pressure | 30% of Injection Pressure | 30% of Injection Pressure | 30% of Injection Pressure | 30% of Injection Pressure |
| Injection Velocity in/s | 2.0 - 3.0 | 2.0 - 3.0 | 2.0 - 3.0 | 2.0 - 3.0 | 2.0 - 3.0 |
| Back Pressure psi | 25 - 100 | 25 - 100 | 25 - 100 | 25 - 100 | 25 - 100 |
| Screw Speed rpm | 30 - 75 | 30 - 75 | 30 - 75 | 30 - 75 | 30 - 75 |
| Drying Parameters °C (°F) | 4hrs @ 82 (180) | 4hrs @ 82 (180) | 4hrs @ 82 (180) | 4hrs @ 82 (180) | 4hrs @ 82 (180) |
| Cushion in | 0.125 - 0.250 | 0.125 - 0.250 | 0.125 - 0.250 | 0.125 - 0.250 | 0.125 - 0.250 |
| Screw Compression Ratio | 3.0:1 | 2.5:1 | 2.5:1 | 2.5:1 | 2.5:1 |
| Nozzle Type | Reverse Taper | Reverse Taper | Reverse Taper | Reverse Taper | Reverse Taper |
| Clamp Pressure | 2 - 3 Tons/in ² | 3 - 5 Tons/in ² | 3 - 5 Tons/in ² | 3 - 5 Tons/in ² | 3 - 5 Tons/in ² |
| Cooling Time Seconds | 10 - 40 | 10 - 40 | 10 - 40 | 10 - 40 | 10 - 40 |
| Screw Type | Bimetallic Screw L/D Ratio = 20:1 | Bimetallic Screw L/D Ratio = 20:1 | Bimetallic Screw L/D Ratio = 20:1 | Bimetallic Screw L/D Ratio = 20:1 | Bimetallic Screw L/D Ratio = 20:1 |

| STARTUP & SHUTDOWN | RECOMMENDATIONS |
|-----------------------|---|
| Drying | Drying Nymax 600 Series is recommended at 180°F (82°C) for 4 hours. The recommended moisture level by weight for unreinforced and less than 20% reinforced compounds is 0.10%-0.20%. For compounds that are greater than 20% reinforced, moisture level of 0.06%-0.12% is recommended. Moisture levels below 0.02% are not recommended. |
| Purge Compound | Polypropylene |
| Coloring | Contact your PolyOne representative. |
| Recycling | Nymax 600 Series is fully recyclable. Conventional granulators with sharp blades should be used. Consistent regrind usage of up to 20% is permissible. Excessive fines or dust-like particles should be avoided. Drying regrind for 4 hours at 180°F (82°C) is recommended. |

| MOLD DESIGN | RECOMMENDATIONS |
|------------------------|---|
| Tool Steel | <ol style="list-style-type: none"> 1. For unreinforced nylon 6 compounds, P20 tool steel is recommended. 2. For reinforced nylon 6 compounds, S7/H13/420 tool steel is recommended to help reduce wear. |
| Gates | <ol style="list-style-type: none"> 1. All types of gates can be used such as pin, fan, tunnel, tab and edge gates. Gate type should be selected based on location and part geometry. 2. Gate diameters should be equivalent to 50%-80% of the average wall thickness of the part to be injected. 3. A land length of 0.040" (1.0mm) is recommended. |
| Runners | <ol style="list-style-type: none"> 1. Full-round or modified trapezoid runners are the best design and provide the least surface to cross-section ratio. Half-round or standard trapezoid runners are not recommended. 2. Only naturally balanced runner systems ("H" pattern) are recommended. 3. Each 90° bend in the system should step down in size. 4. Vents should be placed at the intersection of each 90° bend off of the cold slug well and vented to atmosphere. 5. Hot runner molds are acceptable and should be sized by the manufacturer. Externally heated manifolds are recommended. |
| Cold Slug Wells | <ol style="list-style-type: none"> 1. Place cold slug wells at the base of the sprue to capture the cold material first emerging from the nozzle. 2. Place cold slug wells at every 90° bend in the runner system. 3. Well depths approximately 2-3 times the diameter of the runner provide best results. |
| Venting | <ol style="list-style-type: none"> 1. Place vents at the end of fill and anywhere potential knit/weld lines will occur. 2. All vents need to be vented to atmosphere. 3. For unreinforced nylon 6 compounds, cut vent depths to 0.0005"-0.001" with a minimum 0.030" land length. Increase the vent depth to 0.010" at 0.100" away from the cavity and vent to atmosphere. 4. For reinforced nylon 6 compounds (greater than 20% filler), cut vent depths to 0.001"-0.002" with a minimum 0.030" land length. Increase the vent depth to 0.010" at 0.100" away from the cavity and vent to atmosphere. 5. Vents should be placed at the intersection of each 90° bend in the runner system off of the cold slug well and vented to atmosphere. |
| Draft Angle | <ol style="list-style-type: none"> 1. Draft angle should be 1/2°-1° per side. Additional draft may be required for grained/textured surfaces. |

TROUBLESHOOTING RECOMMENDATIONS

| Problem | Cause | Solution |
|--|------------------------------|--|
| Incomplete Fill | Melt and/or mold too cold | <ol style="list-style-type: none"> 1. Increase nozzle and barrel temperatures 2. Increase mold temperature 3. Increase injection rate 4. Increase pack and hold pressure 5. Increase nozzle tip diameter 6. Check thermocouples and heater bands |
| | Mold design | <ol style="list-style-type: none"> 1. Enlarge or widen vents and increase number of vents 2. Check that vents are unplugged 3. Check that gates are unplugged 4. Enlarge gates and/or runners 5. Perform short shots to determine fill pattern and verify proper vent location 6. Increase wall thickness to move gas trap to parting line |
| | Shot size | <ol style="list-style-type: none"> 1. Increase shot size 2. Increase cushion |
| Brittleness | Low melt temperature | <ol style="list-style-type: none"> 1. Increase melt temperature 2. Increase injection rate 3. Measure melt temperature with pyrometer |
| | Degraded/Overheated material | <ol style="list-style-type: none"> 1. Decrease melt temperature 2. Decrease back pressure 3. Use smaller barrel/excessive residence time |
| | Gate location and/or size | <ol style="list-style-type: none"> 1. Relocate gate to nonstress area 2. Increase gate size to allow higher flow rate and lower molded-in stress |
| Fibers/Minerals on Surface or Uneven Surface Appearance | Melt temperature too low | <ol style="list-style-type: none"> 1. Increase melt temperature 2. Increase mold temperature 3. Increase injection speed |
| | Insufficient packing | <ol style="list-style-type: none"> 1. Increase pack and hold pressure, and time 2. Increase shot size |
| Sink Marks | Part geometry too thick | <ol style="list-style-type: none"> 1. Reduce wall thickness 2. Reduce rib thickness |
| | Melt too hot | <ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature |
| | Insufficient material volume | <ol style="list-style-type: none"> 1. Increase shot size 2. Increase injection rate 3. Increase packing pressure 4. Increase gate size |
| Flash | Injection pressure too high | <ol style="list-style-type: none"> 1. Decrease injection pressure 2. Increase clamp pressure 3. Decrease injection rate 4. Increase transfer position |
| | Excess material volume | <ol style="list-style-type: none"> 1. Decrease pack pressure 2. Decrease shot size 3. Decrease injection rate |
| | Melt and/or mold too hot | <ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature 3. Decrease screw speed |

TROUBLESHOOTING RECOMMENDATIONS

| Problem | Cause | Solution |
|--------------------------|-------------------------------------|---|
| Excessive Shrink | Too much orientation | <ol style="list-style-type: none"> 1. Increase packing time and pressure 2. Increase hold pressure 3. Decrease melt temperature 4. Decrease mold temperature 5. Decrease injection speed 6. Decrease screw rpm 7. Increase venting 8. Increase cooling time |
| Not Enough Shrink | Too little orientation | <ol style="list-style-type: none"> 1. Decrease packing pressure and time 2. Decrease hold pressure 3. Increase melt temperature 4. Increase mold temperature 5. Increase injection speed 6. Increase screw rpm 7. Decrease cooling time |
| Burning | Melt and/or mold too hot | <ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature 3. Decrease injection rate |
| | Mold design | <ol style="list-style-type: none"> 1. Clean, widen and increase number of vents 2. Increase gate size or number of gates. |
| | Moisture | <ol style="list-style-type: none"> 1. Verify material is dried at proper conditions |
| Nozzle Drool | Nozzle temperature too hot | <ol style="list-style-type: none"> 1. Decrease nozzle temperature 2. Decrease back pressure 3. Increase screw decompression 4. Verify material has been dried at proper conditions |
| Weld Lines | Melt front temperatures are too low | <ol style="list-style-type: none"> 1. Increase pack and hold pressure 2. Increase melt temperature 3. Increase vent width and locations 4. Increase injection rate 5. Increase mold temperature |
| | Mold design | <ol style="list-style-type: none"> 1. Decrease injection rate 2. Increase gate size 3. Perform short shots to determine fill pattern and verify proper vent location 4. Add vents and/or false ejector pin 5. Move gate location |
| Warp | Excessive orientation | <ol style="list-style-type: none"> 1. Increase cooling time 2. Increase melt temperature 3. Decrease injection pressure and injection rate |
| | Mold design | <ol style="list-style-type: none"> 1. Increase number of gates |
| Sticking in Mold | Cavities are overpacked | <ol style="list-style-type: none"> 1. Decrease injection rate and pressure 2. Decrease pack and hold pressure 3. Decrease nozzle and barrel temperatures 4. Decrease mold temperature 5. Increase cooling time |
| | Mold design | <ol style="list-style-type: none"> 1. Increase draft angle |
| | Part is too hot | <ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature 3. Increase cooling time |

For questions or issues, please call Global Engineered Materials Technical Support at: 440.930.1000